

## **Monty Software History**

### **November 2009**

Version 4.2.0  
23 November 2009

Fixed bug that prevented registration of licence number entry.

Version 4.1.0  
22 May 2009

Some fixes resulting from new version 4.0.  
Serial Number entry now required on new Registration page.  
Installer now re-boots computer when finished installing. This corrects some issues with registry entries. Advice re "close all programs before installing", added to install instructions.  
Can now accept computers with serial ports ranging up to COM64.

Version 4.0  
8 may 2009

Install process changed to avoid earlier issues of licensing registration errors.  
Serial bit rate choice extended to 115200 Baud for use with USB port.  
Data transfer action changed to eliminate need for EPD command. Data is now sent before embossing.

Version 3.6 and prior.

MB software update V4.7. Command EPD added to Mountbatten to allow for data download change.